



AGENDA


- 1. Introductions
- 2. Process & Timeline
- 3. Community Feedback
- 4. Proposed Concepts
- 5. Next Steps









FEASIBILITY STIINY



TIMELINE






KEY DATES:

- Community Meeting #1 was held on May 20
- Staff Meeting was held on May 27
- Community Meeting #2 was held on June 2
- Community Meeting #3 was held on June 27
- Community Meeting #4 September 16 @
 6:00 pm; in person




COMMUNITY MEETING 1 - ILLUMINATE







Observations:

- Circulation
- Main Entrance
- Adjacencies






COMMUNITY MEETING 1 - WHAT WE HEARD








- Community members inquired about preserving the open space including fields and playgrounds.
- Consider established relationship with City of Rockville.
- Handicap access for playgrounds is a concern.
- There are issues with the current site and building including the electrical and plumbing systems. The building is perceived as 'old & dated' and navigation within the school is challenging.
- Students benefit from the wide variety of after school activities including soccer, 'girls on the run' and an on site after school program with final pickup 6:30pm.
- Many parents use public transit or walk as many community members do not have access to cars.


COMMUNITY MEETING 2 - INNOVATE















COMMUNITY MEETING 2 - WHAT WE HEARD






- Community use of the gym and adjacent parking is important.
- Use of Wainwright Ave for school traffic is a concern as this is a one-way road.
- Preference for an approach that has visibility to playgrounds and play areas from the surrounding public streets.
- The bus loop configuration must allow the bus driver to view the students entering the building.
- The existing driveway and turnaround next to the daycare is a safety concern.
- Inquiries were made regarding tree preservation and grading.

COMMUNITY MEETING 3 - INNOVATE








PROGRAM

		MCPS ED SPEC		EXISTING						
CLASSROOMS		EO-SPEC		EXISTING		CLASSROOMS	ED-SPEC		EXISTING	
Prekindergarten		2	1200	2	subtotal	4th GRADE			1	850
	PRE-K			1	1391	5th GRADE			1	882
	PRE-K			1	1283	5th GRADE			1	867
Storage		1 each 250 sf incl.		2		5th GRADE			1	855
Kindergarten		4 Learly 250 of incl.	1200	5	subtotal 760	5th GRADE			1	819
Storage		1 each 250 sf incl.		5	760 1476	5th GRADE			1	814
	Kindergarten			1	1476	5th GRADE			1	808
	Kindergarten			1		Art	1	1200	1	1189
	Kindergarten			1	1037	Storage	teach 250 sf incl		2	100
	Kindergarten			1	967	Music	1	1200	1	870
	Kindergarten			- 1	905	Storage	1 each 250 sf incl.		0	0
Standard Clas	isrooms	24 Leach 250 of incl.	850	23	subtotal	Instrumental Music	1	450	0	0
Storage	1st GRADE	leach 250 st incl.		9	48 811	Dual Purpose Room	1	1000	0	
	1st GRADE			1	809		AREA SUBTOTAL :	31,450		31,529
	1st GRADE			1						
	1st GRADE 1st GRADE			1	775 731	SUPPORT ROOMS Resource Rooms	ED SPEC		EXISTING	
				1	956		0	0	3	subtotal
	2nd GRADE			1					1	821
	2nd GRADE 2nd GRADE			1	953				1	748
				1	929				1	517
	2nd GRADE			1	917	Large Instructional Support	1	550	1	339
	3rd GRADE			1	887	Small Instructional Support Room	2	425	3	304
	3rd GRADE			1	880	Speech Lanuage Therapy	1	250	2	274
	3rd GRADE			1	858	Therapy Support Room	1	250	1	102
	3rd GRADE	1		1	850	Personal Care Room	1	100	0	120
	4th GRADE	l		1	962	Testing / Conference Room	1	140	0	0
	4th GRADE			1	887	Support Staff Offices	2	140	1	325
	4th GRADE	l		1	880	Parent Resource Room	1	500	1	0
	4th GRADE			1	858		ARFA SURTOTAL	2 370		4 312





EXISTING CONDITIONS









- and 2-stories, connected via stairs and ramps.

- Interior building signage is not ADA

APPROACHES & COMMON TRAITS

General:

- Compliance with accessibility standards, building & site.
- Option 1, 2, & 3: Reuse of existing building

Site:

- Soccer Field & Softball Field provided
- All play areas provided in options 2, 3, & 4 meet MCPS standards.
- Bus loop and student drop off located at main entrance in options 2, 3, & 4.

Building:

- New Building Systems (mechanical, electrical, plumbing, sprinkler)
- New Finishes throughout
- **New Windows**
- All MCPS Educational Specification space provided in options 2,3, & 4.

COMMUNITY MEETING 3 - WHAT WE HEARD





- Option 4, New Construction, was the preferred option.
- The school needs to reflect how great Twinbrook is as a community.
- Twinbrook community should have a premier school for their children.
- Larger classrooms, open space and a community garden is important to the school.
- Community advocated for sustainable features like photovoltaic panels, green roofs and storm rainfall collection.
- Community advocated for onsite daycare to be included within the school.
- The staff rooms need to be convenient for all teachers to use.




FOUR APPROACHES


* Add Alternates not included.


OPTION		DEMOLITION	RENEWAL	RENOVATION	NEW CONSTRUCTION	EST. CONSTRUCTION COST		
1	Total Building after Renewal = 79,750 GSF Net assignable SF = 54,191 NSF Efficiency = 69%	Total = 0 GS	Main Level Lower Level Total = 71,802 GSF		Total = 0 GSF	\$ \$\$ \$\$\$\$\$\$\$		
2	Total Building after Renewal = 78,609 GSF Net assignable SF = 56,842 NSF Efficiency = 72% *	Main Level Lower Level Total = 30,913 GS		Total = 12,192 GSF	Total = 29,772 GSF	\$ \$\$ \$\$\$\$\$		
3	Total Building after Renewal = 80,505 GSF Net assignable SF = 56,879 NSF Efficiency = 71% *	Main Level Lower Level Total = 40,813 GS			Main Level Upper Level Total = 41,568 SF	\$ \$\$ \$\$\$ \$ \$\$		
4	Total Building after Renewal = 79,668 GSF Net assignable SF = 54,012 NSF Efficiency = 68% *	Main Level Lower Lever Total = 79,750 GS			Main Level Upper Level Total = 79,668 GSF	\$ \$\$ \$\$\$\$\$\$		

OPTION 1 - RENEWAL SUMMARY




Option 1 -Renewal SUMMARY 70,750 GSF - Renewal 7,948 GSF - Renovation AREA 69% - Gross Efficiency **Building Renovation New Elevator** Electrical & Plumbing system replacement Renovate finishes SCOPE Gender Neutral Restroom upgrade Accessibility Standard renovations for site and building Maintain location of play areas and fields Maintain location of parking, car and bus drop offs.





OPTION 1 - RENEWAL



Area Summary:

70,750 GSF - Renewal 7,948 GSF - Renovation 69% - Gross Efficiency


Pros:

- Sprinkler system added
- New building systems
- Addresses accessibility issues
- Community-sized gym remains
- Cost effective
- Sustainable finish building materials
- Shortest Construction Schedule
- Compartmentalization added with new firewalls

Cons:

- Cannot accommodate program spaces:
 Dual-Purpose Room, Music, Instrumental Music, Kitchen support spaces.
- Rooms undersized: Administration, Health Services, 5 Classrooms, Multi-Purpose Room, & Kitchen
- No lockers in corridors
- Low visibility to playgrounds
- Low visibility to main entrance
- Does not address safety concerns at Daycare drop off
- Type V-B Construction remains

OPTION 2 - LESS THAN 50% DEMO - SUMMARY



Option 2 -Less than 50% Demo


EA SUMMARY

30,913 GSF - Demolition 36,645 GSF - Renewal 12,192 GSF - Renovation 29,772 GSF - Addition 72% - Efficiency


- Building Additions added to meet program requirements.
- Electrical & Plumbing system replacement
- Renovate finishes

SCOPE

- Restroom upgrade
- Accessibility Standard renovations
- · Maintain location of fields
- New location for parking, car and bus drop offs
- New location for play areas



OPTION 2 - LESS THAN 50% DEMO



Area Summary:

30,913 GSF - Demolition 36,645 GSF - Renewal 12,192 GSF - Renovation 29,772 GSF - Addition


Pros:

- Sprinkler system added
- Replaces outdated building systems
- Addresses accessibility issues
- Design meets ed spec
- Community-sized gym
- Compartmentalization added with new firewalls
- Sustainable finish building materials.
- New Daycare drop off
- 1-Story building

Cons:

- Lockers cannot fit in existing corridors
- Low visibility to playgrounds
- Type V-B Construction remains
- No daylight in Media Center & Resource Rooms.

OPTION 3 - MORE THAN 50% DEMO - SUMMARY



Option 3 -More than 50% Demo


REA SUMMARY


40,813 GSF - Demolition 28,971 GSF - Renewal 9,966 GSF - Renovation 41,568 GSF - Addition 71% - Efficiency

- New Building Additions
- Electrical & Plumbing system replacement
- · Renovate finishes


SCOPE

- Gender Neutral Restroom upgrade
- Accessibility Standard renovations
- · Maintain location of fields
- New location for parking, car and bus drop offs
- New locations for play areas





OPTION 3 - MORE THAN 50% DEMO



Area Summary:

40,813 GSF - Demolition 28,971 GSF - Renewal 9,966 GSF - Renovation 41,568 GSF - Addition 71% - Efficiency


Pros:

- Sprinkler system added
- Replaces outdated building systems
- Addresses accessibility issues
- Compartmentalization added with new firewalls
- Design meets ed spec
- · Community-sized gym
- Sustainable building materials
- Simple Internal circulation
- Smaller building footprint
- New daycare drop off


Cons:


- Lockers cannot fit in existing corridors
- · Low visibility to play areas
- No daylight in Library Media Center
- Type V-B Construction remains
- Multiple parking lots.

OPTION 4 - REPLACEMENT - SUMMARY




Option 4 -Replacement AREA SUMMARY 79,750 GSF - Demolition 79,668 GSF - Addition 68% - Efficiency Existing building is demolished New building New play areas SCOPE Relocate site program and circulation New location for play areas and fields New location for parking, car and bus drop offs





OPTION 4 - REPLACEMENT



Area Summary:

79,750 GSF - Demolition 79,668 GSF - Addition 68% - Efficiency


Pros:

- All new construction
- Fully Accessible
- Design meets ed spec requirements
- Sustainable building materials.
- Small building footprint
- Good room adjacencies
- Good visibility to play areas
- Community gathering space


Cons:

- High impact to the site = higher cost
- Community-sized gym is an add alternate
- Longer on-site vehicular circulation
- High volume of construction waste.
- Bus traffic on Wainright Avenue.

SUMMARY




POTENTIAL SCHEDULE - OPTION 1




^{*} The actual calendar years are to be determined.

POTENTIAL SCHEDULE - OPTIONS 2, 3 & 4



^{*} The actual calendar years are to be determined.

NEXT STEPS



• October 6, 2025 at 6:30pm: City of Rockville Mayor and Council Meeting

Capital Improvements Program (CIP) Timeline

- October 13, 2025: Superintendent published recommendations for the FY 2027
 Capital Budget and the FY 2027-2032 CIP
- October 14, 2025: Facilities and Boundaries Preliminary Presentation and Work
 Session
- October 23, 2025: Facilities and Boundaries Public Hearing #1
- October 28, 2025: Facilities and Boundaries Public Hearing #2
- November 4, 2025: Facilities and Boundaries Work Session #2
- November 6, 2025: Facilities and Boundaries Work Hearing #3 (if needed)
- November 11, 2025: Facilities and Boundaries Work Session #3 (if needed)



